

Product Information

Product Brand: Roto Safe

Phase out H600 strong

Related Products

Roto Safe
Discontinued Product

Availability / Ordering ability

The H600 locks listed below will be changed to H650.

Technical background of this changeover:

Revision of the main lock to improve the customer benefit position:
increase of reliability, product safety, stability, functionality and improved ease of assembly
increase of the maximum permissible handle force to 20 kg
efficiency increase
travel reduction

geplanter Umstellungstermin

When the pre-produced stock is used up, the replacements are released.
You will be informed about this via the PI.

Spare parts

Are not intended.

Return shipments are not possible!

30.06.2022 Update

The remaining H600 locks (see phase-out date 30.06.2022) have now been removed from the program.
Exception: Mat. 858923 (China in clarification).
Remaining stocks (FERT and basic locks) are available and should be used up before ordering the H650.
The replacement models have also been released and can be ordered immediately.

29.06.2022 Update

For locks (see phase-out date 29.06.2022), the pre-produced stock has been used up. These will now be taken out of the program with immediate effect.
Only remaining stocks can be sold. A reproduction is not possible.
The replacements are also released with immediate effect and can be ordered.

27.06.2022 Update

For lock 822570 (see phase-out date 27.06.2022), the pre-produced stock has been used up. These will now be taken out of the program with immediate effect.
Only remaining stocks can be sold. A reproduction is not possible.
The replacement 2003838 is also released with immediate effect and can be ordered

20.06.2022 Update

For locks 2592P8 (see phase-out date 20.06.2022), the pre-produced stock has been used up. These will now be taken out of the program with immediate effect.

Only remaining stocks can be sold. A reproduction is not possible.

The replacements are also released with immediate effect and can be ordered.

31.05.2022 Update

For locks 4594R8 (see phase-out date 31.05.2022), the pre-produced stock has been used up. These will now be taken out of the program with immediate effect.

Only remaining stocks can be sold. A reproduction is not possible.

The replacements are also released with immediate effect and can be ordered.

23.05.2022 Update

For locks (see phase-out date 23.05.2022), the pre-produced stock has been used up. These will now be taken out of the program with immediate effect.

Only remaining stocks can be sold. A reproduction is not possible.

The replacements are also released with immediate effect and can be ordered.

12.05.2022 Update

For lock 626860 (see phase-out date 12.05.2022), the pre-produced stock has been used up. These will now be taken out of the program with immediate effect.

Only remaining stocks can be sold. A reproduction is not possible.

The replacement 2003494 is also released with immediate effect and can be ordered.

11.05.2022 Update

For locks (see phase-out date 11.05.2022), the pre-produced stock has been used up. These will now be taken out of the program with immediate effect.

Only remaining stocks can be sold. A reproduction is not possible.

The replacements are also released with immediate effect and can be ordered.

10.05.2022 Update

For locks (see phase-out date 10.05.2022), the pre-produced stock has been used up. These will now be taken out of the program with immediate effect.

Only remaining stocks can be sold. A reproduction is not possible.

The replacements are also released with immediate effect and can be ordered.

06.05.2022 Update

For locks (see phase-out date 06.05.2022), the pre-produced stock has been used up. These will now be taken out of the program with immediate effect.

Only remaining stocks can be sold. A reproduction is not possible.

The replacements are also released with immediate effect and can be ordered.

04.05.2022 Update

For lock 637637 (see phase-out date 04.05.2022), the pre-produced stock has been used up. These will now be taken out of the program with immediate effect.

Only remaining stocks can be sold. A reproduction is not possible.

The replacement 2003562 is also released with immediate effect and can be ordered.

02.05.2022 Update

For lock 735199 (see phase-out date 02.05.2022), the pre-produced stock has been used up. These will now be taken out of the program with immediate effect.

Only remaining stocks can be sold. A reproduction is not possible.

The replacement 2003561 is also released with immediate effect and can be ordered.

26.04.2022 Update

For locks (see phase-out date 26.04.2022), the pre-produced stock has been used up. These will now be taken out of the program with immediate effect.

Only remaining stocks can be sold. A reproduction is not possible.

The replacements are also released with immediate effect and can be ordered.

21.04.2022 Update

For locks (see phase-out date 21.04.2022), the pre-produced stock has been used up. These will now be taken out of the program with immediate effect.

Only remaining stocks can be sold. A reproduction is not possible.

The replacements are also released with immediate effect and can be ordered.

12.04.2022 Update

For locks (see phase-out date 12.04.2022), the pre-produced stock has been used up. These will now be taken out of the program with immediate effect.

Only remaining stocks can be sold. A reproduction is not possible.

The replacements are also released with immediate effect and can be ordered.

08.04.2022 Update

For locks (see phase-out date 08.04.2022), the pre-produced stock has been used up. These will now be taken out of the program with immediate effect.

Only remaining stocks can be sold. A reproduction is not possible.

The replacements are also released with immediate effect and can be ordered.

30.03.2022 Update

For locks (see phase-out date 30.03.2022), the pre-produced stock has been used up. These will now be taken out of the program with immediate effect.

Only remaining stocks can be sold. A reproduction is not possible.

The replacements are also released with immediate effect and can be ordered.

28.02.2022 Update

For the first locks, the pre-produced stock has been used up. These will now be taken out of the program with immediate effect.

(see phase-out date 28.02.2022).

Only remaining stocks can be sold. A reproduction is not possible.

The replacements are also released with immediate effect and can be ordered.

Product Overview Outlet

Material No.	Description	Phase-Out Date	Target CPMS	Note
609153	H600 2892P8 2200F2x16SIL 4V 2225 VE100	26.04.2022	81	Nachfolger/replacement 2003437

609158	H600 4592P8 2200F2x16SIL 4V 2225 VE100	10.05.2022	81	Nachfolger/replacement 2003440
609159	H600 3592P8 2200F2x16SIL 4V 2225 VE100	30.03.2022	81	Nachfolger/replacement 2003438
609160	H600 3592P8 2200F3x16SIL 2CB 0203 VE100	30.03.2022	80	kein Nachfolger/no replacement
609161	H600 3592P8 2200F3x16SIL 2C 0203	30.03.2022	81	Nachfolger/replacement 2003482
609162	H600 4092P8 2200F2x16SIL 4V 2225 VE100	28.02.2022	81	Nachfolger/replacement 2003439
609163	H600 2592P8 2200F2x16SIL 4V 2225	20.06.2022	81	Nachfolger/replacement 2003430
609163	H600 2592P8 2200F2x16SIL 4V 2225	30.06.2022	81	Nachfolger/replacement 2003430
611305	H600 2592P8 2200F3x16SIL 2CH 0203	20.06.2022	99	Nachfolger/replacement 2003520
611306	H600 2592P8 2200F3x16SIL 2C 0203	20.06.2022	99	Nachfolger/replacement 2003480
611307	H600 2592P8 2200F3x16SIL 2CB 0203	20.06.2022	99	Nachfolger/replacement 2003500
611308	H600 2592P8 2200F2x16STS 2CH 0203	20.06.2022	99	kein Nachfolger/no replacement
611309	H600 2592P8 2200F2x16STS 2C 0203	20.06.2022	99	kein Nachfolger/no replacement
611310	H600 2592P8 2200F2x16STS 2CB 0203	20.06.2022	99	kein Nachfolger/no replacement
611311	H600 2892P8 2200F3x16SIL 2CH 0203	21.04.2022	81	Nachfolger/replacement 2003521
611312	H600 2892P8 2200F3x16SIL 2C 0203	21.04.2022	81	Nachfolger/replacement 2003481
611313	H600 2892P8 2200F3x16SIL 2CB 0203	21.04.2022	81	Nachfolger/replacement 2003501
611314	H600 2892P8 2200F2x16STS 2CH 0203	21.04.2022	80	kein Nachfolger/no replacement
611315	H600 2892P8 2200F2x16STS 2C 0203	21.04.2022	80	kein Nachfolger/no replacement
611316	H600 2892P8 2200F2x16STS 2CB 0203	21.04.2022	80	kein Nachfolger/no replacement
611317	H600 2892P8 2200F2x16SIL 4V 2225	29.06.2022	81	Nachfolger/replacement 2003431
611318	H600 3592P8 2200F2x16SIL 4V 2225	30.03.2022	81	Nachfolger/replacement 2003432
611319	H600 4092P8 2200F2x16SIL 4V 2225	28.02.2022	81	Nachfolger/replacement 2003433
611320	H600 3592P8 2200F2x16SIL 4E 2225 VE100	30.03.2022	81	Nachfolger/replacement 2003475
611321	H600 4592P8 2200F2x16SIL 4E 2225 VE100	10.05.2022	81	Nachfolger/replacement 2003476
611322	H600 5592P8 2200F2x16SIL 4E 2225 VE100	08.04.2022	99	Nachfolger/replacement 2003478
611323	H600 3592P8 2200F2x16STS 2CB 0203	30.03.2022	80	kein Nachfolger/no replacement
611324	H600 3592P8 2200F2x16STS 2C 0203	30.03.2022	80	kein Nachfolger/no replacement
611325	H600 4092P8 2200F3x16SIL 2CB 0203 VE100	28.02.2022	80	kein Nachfolger/no replacement
611326	H600 4092P8 2200F3x16SIL 2C 0203	28.02.2022	81	Nachfolger/replacement 2003483
611327	H600 4092P8 2200F2x16STS 2CB 0203	28.02.2022	80	kein Nachfolger/no replacement
611328	H600 4092P8 2200F2x16STS 2C 0203	28.02.2022	80	kein Nachfolger/no replacement
611329	H600 4592P8 2200U6x24SIL 2CB 0203 VE100	06.05.2022	99	kein Nachfolger/no replacement
611330	H600 4592P8 2200U6x24SIL 2C 0203	06.05.2022	81	Nachfolger/replacement 2003490
611331	H600 4592P8 2200U6x24STS 2CB 0203	06.05.2022	99	kein Nachfolger/no replacement
611332	H600 4592P8 2200U6x24STS 2C 0203	06.05.2022	80	kein Nachfolger/no replacement
611333	H600 4592P8 2200F3x16SIL 2CB 0203	10.05.2022	81	Nachfolger/replacement 2003504

611334	H600 4592P8 2200F3x16SIL 2C 0203	10.05.2022	81	Nachfolger/replacement 2003484
611335	H600 4592P8 2200F2x16STS 2CB 0203	06.05.2022	99	kein Nachfolger/no replacement
611336	H600 4592P8 2200F2x16STS 2C 0203	06.05.2022	80	kein Nachfolger/no replacement
611337	H600 5592P8 2200F3x16SIL 2CB 0203	08.04.2022	81	Nachfolger/replacement 2003505
611338	H600 5592P8 2200F3x16SIL 2C 0203	12.04.2022	81	Nachfolger/replacement 2003485
611339	H600 5592P8 2200F2x16STS 2CB 0203	08.04.2022	80	kein Nachfolger/no replacement
611340	H600 5592P8 2200F2x16STS 2C 0203	08.04.2022	99	kein Nachfolger/no replacement
611341	H600 3592P8 2200F3x16SIL 2CH 0203	30.03.2022	81	Nachfolger/replacement 2003522
611342	H600 3592P8 2200F2x16STS 2CH 0203	30.03.2022	80	kein Nachfolger/no replacement
611712	H600 4592P8 2200F2x16SIL 4V 2225	10.05.2022	81	Nachfolger/replacement 2003434
620679	H600 5592P8 2100F3x16SIL 2CB 0203 KO	12.04.2022	81	Nachfolger/replacement 2003517
620680	H600 5592P8 2100F3x16SIL 2C 0203 KO	12.04.2022	81	Nachfolger/replacement 2003495
623936	H600 2592P8 2200F2x16SIL 4E 2225	20.06.2022	81	Nachfolger/replacement 2003468
626549	H600 4592P8 2200F3x16SIL 2CBZS 0217	10.05.2022	81	Nachfolger/replacement 2003538
626550	H600 3592P8 2200F3x16SIL 2CBZS 0217	30.03.2022	81	Nachfolger/replacement 2003536
626551	H600 5592P8 2200F3x16SIL 2CBZS 0217	12.04.2022	81	Nachfolger/replacement 2003539
626552	H600 4092P8 2200F3x16SIL 2CBZS 0217	28.02.2022	81	Nachfolger/replacement 2003537
626858	H600 3592P8 2200F2x16SIL 4E 2225	30.03.2022	81	Nachfolger/replacement 2003470
626859	H600 4592P8 2200F2x16SIL 4E 2225	10.05.2022	81	Nachfolger/replacement 2003472
626860	H600 5592P8 2200F2x16SIL 4E 2225	12.05.2022	81	Nachfolger/replacement 2003473
626861	H600 4092P8 2200F3x16SIL 2CB 0203	28.02.2022	81	Nachfolger/replacement 2003503
626862	H600 4592P8 2200U6x24SIL 2CB 0203	10.05.2022	81	Nachfolger/replacement 2003513
626863	H600 3592P8 2200F3x16SIL 2CB 0203	30.03.2022	81	Nachfolger/replacement 2003502
627161	H600 4592P8 2200F2x16SIL 2ZK 3663 VE100	06.05.2022	99	kein Nachfolger/no replacement
627172	H600 4592P8 2200F2x20SIL 4V 2225	10.05.2022	81	Nachfolger/replacement 2003464
627176	H600 5592P8 2000F2x16SIL 2ZK 3661 VE100	08.04.2022	99	kein Nachfolger/no replacement
627185	H600 4092P8 2200F2x16SIL 4E 2225	28.02.2022	81	Nachfolger/replacement 2003471
627186	H600 4592P8 1900U6x24SIL 2CB 0205	10.05.2022	81	Nachfolger/replacement 2003514
627187	H600 2892P8 2200F2x16SIL 4E 2225 VE100	21.04.2022	81	Nachfolger/replacement 2003474
627215	H600 2892P8 2200F2x16SIL 4E 2225	23.05.2022	81	Nachfolger/replacement 2003469
627216	H600 5592P8 2200F2x16SIL 4V 2225 VE100	23.05.2022	81	Nachfolger/replacement 2003441
627217	H600 5592P8 2200F2x16SIL 4V 2225	29.06.2017	81	Nachfolger/replacement 2003435
627218	H600 3592P8 2165F2x16SIL 4V 1825 ZO	30.03.2022	81	Nachfolger/replacement 2003444
627219	H600 4592P8 2200F2x16SIL 2CB2V 5253 ZOZU	30.06.2022	81	Nachfolger/replacement 2003551
627220	H600 3592P8 2200F2x16SIL 2CB2V 5253 ZOZU	30.03.2022	81	Nachfolger/replacement 2003549
627221	H600 4092P8 2200F2x16SIL 2CB2V 5253 ZOZU	28.02.2022	81	Nachfolger/replacement 2003550

627222	H600 5592P8 2200F2x16SIL 2CB2V 5253 ZOZU	12.04.2022	81	Nachfolger/replacement 2003552
627223	H600 6592P8 2200F2x16SIL 2CB2V 5253 ZOZU	30.06.2022	81	Nachfolger/replacement 2003553
627224	H600 6592P8 2200F2x16SIL 4V 2225	30.06.2022	81	Nachfolger/replacement 2003436
627225	H600 4592P8 2200F3x20SIL 2CB 0203 VZS	30.06.2022	81	Nachfolger/replacement 2003519
627227	H600 6592P8 2200F3x16SIL 2CB 0203	30.06.2022	81	Nachfolger/replacement 2003506
627229	H600 4592P8 2200F2x20SIL 2CB2V 5253 ZOZU	06.05.2022	81	Nachfolger/replacement 2003554
627230	H600 4592P8 2200F3x16SIL 2CB 0203 VZS	30.06.2022	81	Nachfolger/replacement 2003518
627231	H600 4594R8 2200F3x16SIL 2CB 0203	31.05.2022	80	kein Nachfolger/no replacement
627340	H600 6594R8 2200F2x16SIL 4V 2225	30.06.2022	80	kein Nachfolger/no replacement
628154	H600 2592P8 2200F2x16SIL 4V 2225 ZUOV	30.06.2022	81	Nachfolger/replacement 2003447
628154	H600 2592P8 2200F2x16SIL 4V 2225 ZUOV	20.06.2022	81	Nachfolger/replacement 2003447
628165	H600 2892P8 2200F2x16SIL 4V 2225 ZUOV	21.04.2022	81	Nachfolger/replacement 2003448
628165	H600 2892P8 2200F2x16SIL 4V 2225 ZUOV	30.06.2022	81	Nachfolger/replacement 2003448
628166	H600 3592P8 2200F2x16SIL 4V 2225 ZUOV	30.03.2022	81	Nachfolger/replacement 2003449
628167	H600 4092P8 2200F2x16SIL 4V 2225 ZUOV	28.02.2022	81	Nachfolger/replacement 2003450
628168	H600 4592P8 2200F2x16SIL 4V 2225 ZUOV	30.06.2022	81	Nachfolger/replacement 2003451
628169	H600 3592P8 2200U6x24STS 2C 0203	30.03.2022	80	kein Nachfolger/no replacement
628170	H600 3592P8 2200U6x24STS 2CB 0203	30.03.2022	81	Nachfolger/replacement 2003515
628171	H600 3592P8 2200U6x24STS 2CH 0203	30.03.2022	80	kein Nachfolger/no replacement
628786	H600 4592P8 1120F2x16SIL 1K 0073 ZO	30.06.2022	81	Nachfolger/replacement 2003558
629196	H600 2592P8 2165F2x16SIL 4V 1825 ZO	20.06.2022	81	Nachfolger/replacement 2003442
629197	H600 2892P8 2165F2x16SIL 4V 1825 ZO	26.04.2022	81	Nachfolger/replacement 2003443
629893	H600 4592P8 2200F3x20SIL 2CBZS 0217	10.05.2022	81	Nachfolger/replacement 2003545
629894	H600 4592P8 2200F3x20SIL 2CHZS 0217	10.05.2022	80	kein Nachfolger/no replacement
629895	H600 4592P8 2200U6x24SIL 2CHZS 0217	10.05.2022	81	Nachfolger/replacement 2003548
629896	H600 4592P8 1900F3x16SIL 2CH 0205	10.05.2022	81	Nachfolger/replacement 2003525
629898	H600 5592P8 2200F3x20SIL 2CHZS 0217	12.04.2022	81	Nachfolger/replacement 2003546
629899	H600 4592P8 2165F2x16SIL 4V 1825 ZO	10.05.2022	81	Nachfolger/replacement 2003445
630062	H600 3592P8 2200F3x16SIL 2CZS 0217	30.03.2022	81	Nachfolger/replacement 2003533
630063	H600 4592P8 2200F3x16SIL 2CZS 0217	10.05.2022	81	Nachfolger/replacement 2003534
630085	H600 5592P8 2200F3x16SIL 2CZS 0217	08.04.2022	99	Nachfolger/replacement 2003535
630086	H600 5592P8 2200F3x20SIL 2CZS 0217	12.04.2022	81	Nachfolger/replacement 2003544
630961	H600 2592P8 404F2x16SIL KOKU	30.06.2022	81	Nachfolger/replacement 2003382
630961	H600 2592P8 404F2x16SIL KOKU	20.06.2022	81	Nachfolger/replacement 2003382
630962	H600 2892P8 404F2x16SIL KOKU	30.06.2022	81	Nachfolger/replacement 2003383
630962	H600 2892P8 404F2x16SIL KOKU	26.04.2022	81	Nachfolger/replacement 2003383

630963	H600 3592P8 404F2x16SIL KOKU	30.06.2022	81	Nachfolger/replacement 2003424
630964	H600 4092P8 404F2x16SIL KOKU	28.02.2022	81	Nachfolger/replacement 2003425
630965	H600 4592P8 404F2x16SIL KOKU	10.05.2022	81	Nachfolger/replacement 2003426
630966	H600 5592P8 404F2x16SIL KOKU	30.06.2022	81	Nachfolger/replacement 2003428
632807	H600 5592P8 2200F3x20SIL 2CH 0203 VZS	30.06.2022	80	kein Nachfolger/no replacement
632959	H600 3592P8 2200F2x16SIL 2V2K 4849 VE100	30.03.2022	80	Nachfolger/replacement 2003562
632960	H600 4592P8 1758F3x20SIL 2H 0203 S2	06.05.2022	99	kein Nachfolger/no replacement
632961	H600 4592P8 1900F3x20SIL 2H 0205 S2	06.05.2022	81	Nachfolger/replacement 2005629
632962	H600 4592P8 2100F3x20SIL 2H 0203 S2	06.05.2022	81	Nachfolger/replacement 2005630
632963	H600 4592P8 2410F3x20SIL 2H 0207 S2	06.05.2022	99	Nachfolger/replacement 2005631
633313	H600 4592P8 2200F2x20SIL 4V 2225 ZUOV	06.05.2022	81	Nachfolger/replacement 2003466
633314	H600 5592P8 2200F2x20SIL 4V 2225 ZUOV	26.04.2022	81	Nachfolger/replacement 2003467
633416	H600 3592P8 2200F3x16SIL 2H 0203 VE100	30.03.2022	81	Nachfolger/replacement 2005636
633417	H600 3592P8 2050F2x16SIL 2H2V 2257 VE100	30.03.2022	81	Nachfolger/replacement 2005659
633935	H600 5592P8 1758R3x20SIL 2H0203 S2VE100	08.04.2022	81	Nachfolger/replacement 2005633
633936	H600 5592P8 1988R3x20SIL 2H0207 S2VE100	08.04.2022	81	Nachfolger/replacement 2005634
633937	H600 5592P8 2090F3x20SIL 2H 0203 S2	08.04.2022	80	kein Nachfolger/no replacement
633938	H600 5592P8 2400F3x20SIL 2H 0207 S2	08.04.2022	80	kein Nachfolger/no replacement
633939	H600 5592P8 1744F3x20SIL 2T 1647 VE100	08.04.2022	80	kein Nachfolger/no replacement
633940	H600 5592P8 1914F3x20SIL 2T 1443 VE100	08.04.2022	80	kein Nachfolger/no replacement
634670	H600 3592P8 2200F3x16SIL 2CHZS 0217	30.03.2022	81	Nachfolger/replacement 2003540
634671	H600 4592P8 2200F3x16SIL 2CHZS 0217	10.05.2022	81	Nachfolger/replacement 2003541
634672	H600 5592P8 2200F3x16SIL 2CHZS 0217	08.04.2022	81	Nachfolger/replacement 2003542
635719	H600 5592P8 1758R3x20SIL 2H 0203 VE100	08.04.2022	81	Nachfolger/replacement 2005637
635720	H600 5592P8 1988R3x20SIL 2H 0207 VE100	08.04.2022	81	Nachfolger/replacement 2005639
636077	H600 4592P8 2200F3x16SIL 2CH 0203	10.05.2022	81	Nachfolger/replacement 2003523
636482	H600 5592P8 2400F3x16SIL 2CB 0207	12.04.2022	81	Nachfolger/replacement 2003510
636895	H600 3592P8 2200F2x16SIL 4V 2225 PL	30.03.2022	81	Nachfolger/replacement 2003457
637519	H600 4092P8 1900F3x16SIL 2CB 0205	28.02.2022	81	Nachfolger/replacement 2003507
637520	H600 2892P8 2200F2x16SIL 4V 2225 ZO STI	26.04.2022	81	Nachfolger/replacement 2003461
637521	H600 4592P8 2200F3x16SIL 4CH 0817	10.05.2022	81	Nachfolger/replacement 2003532
637522	H600 5092P8 2200F2x16SIL 4V 2225 ZUOV	11.05.2022	81	Nachfolger/replacement 2003452
637523	H600 2592P8 2200F2x16SIL 4E 2225 ZUOV OR	20.06.2022	99	kein Nachfolger/no replacement
637524	H600 2892P8 2200F2x16SIL 4E 2225 ZUOV OR	26.04.2022	81	Nachfolger/replacement 2003479
637525	H600 2892P8 2200F2x16SIL 4V 2225 PL	21.04.2022	81	Nachfolger/replacement 2003456
637526	H600 4092P8 2200F2x16SIL 4V 2225 PL	28.02.2022	81	Nachfolger/replacement 2003458

637527	H600 5092P8 2200F2x16SIL 4V 2225 PL	11.05.2022	81	Nachfolger/replacement 2003460
637572	H600 2592P8 2200F2x16SIL 4V 2225 PL	20.06.2022	81	Nachfolger/replacement 2003455
637573	H600 4592P8 2200F2x16SIL 4V 2225 PL	10.05.2022	81	Nachfolger/replacement 2003459
637622	H600 3592P8 2200F2x16SIL 2CH2V 5253 ZOZU	30.03.2022	81	Nachfolger/replacement 2003555
637623	H600 4594R8 2200F2x16SIL 4V 2225 ZUOV	11.05.2022	81	Nachfolger/replacement 2003830
637624	H600 6594R8 2200F2x16SIL 4V 2225 ZUOV	30.06.2022	81	Nachfolger/replacement 2003832
637637	H600 4592P8 2200F2x16SIL 4V 2225 ZO STI	04.05.2022	99	Nachfolger/replacement 2003462
637638	H600 5092P8 2200F2x16SIL 4V 2225 ZO STI	11.05.2022	81	Nachfolger/replacement 2003463
637645	H600 5594R8 2200F2x16SIL 4V 2225 ZUOV	30.06.2022	81	Nachfolger/replacement 2003831
637646	H600 3594R8 2200F2x16SIL 4V 2225 ZUOV	30.06.2022	81	Nachfolger/replacement 2003829
639522	H600 4592P8 2200F2x16SIL 2CH2V 5253 ZOZU	10.05.2022	81	Nachfolger/replacement 2003557
639524	H600 6592P8 2100F3x20SIL 2C 0203 KO	30.06.2022	81	Nachfolger/replacement 2003497
639535	H600 4592P8 2200F3x20SIL 2C 0203 VZS	10.05.2022	81	Nachfolger/replacement 2003498
639570	H600 5594R8 2100F3x16SIL 2C 0203 KO	30.06.2022	81	Nachfolger/replacement 2003839
639571	H600 4594R8 2100F3x16SIL 2C 0203 KO	31.05.2022	81	Nachfolger/replacement 2003837
639572	H600 6594R8 2100F3x16SIL 2C 0203 KO	30.06.2022	81	Nachfolger/replacement 2003840
640264	H600 3592P8 2200U6x24SIL 2CH 0203	30.03.2022	81	Nachfolger/replacement 2003531
640870	H600 AL 4092P8 380U4,5x20STS KOKU	28.02.2022	81	Nachfolger/replacement 2003564
640871	H600 AL 4592P8 380U4,5x20STS KOKU	10.05.2022	81	Nachfolger/replacement 2003565
640979	H600 4592P8 2100F3x16SIL 2C 0203 KO	10.05.2022	81	Nachfolger/replacement 2003494
640980	H600 4592P8 2100F3x20SIL 2C 0203 KO	10.05.2022	81	Nachfolger/replacement 2003496
640981	H600 4592P8 2200F3x20SIL 2CH 0203 VZS	06.05.2022	80	kein Nachfolger/no replacement
640982	H600 6592P8 2200F3x20SIL 2C 0203	30.06.2022	80	kein Nachfolger/no replacement
642281	H600 5592P8 2165F2x16SIL 4V 1825 ZO	08.04.2022	81	Nachfolger/replacement 2003446
643189	H600 5592P8 1758R3x24SIL 2H 0203S2VE100	08.04.2022	81	Nachfolger/replacement 2005635
643479	H600 3592P8 2000F2x20SIL 2ZK 3661	30.03.2022	80	kein Nachfolger/no replacement
643583	H600 4594R8 1900F3x16SIL 2CB 0205	31.05.2022	99	kein Nachfolger/no replacement
730431	H600 5592P8 1388R3x20SIL 2H 0205 VE100	08.04.2022	81	Nachfolger/replacement 2005638
735559	H600 3592P8 2200F3x24SIL 2CH 0203	30.03.2022	81	Nachfolger/replacement 2003530
737086	H600 4592P8 2050F2x16SIL 2CH2V 6089 ZOZU	06.05.2022	99	kein Nachfolger/no replacement
738424	H600 AL 3592P8 380U4,5x20STS KOKU	30.03.2022	81	Nachfolger/replacement 2003566
739172	H600 4592P8 2200F3x20SIL 2CZS 0217	06.05.2022	99	Nachfolger/replacement 2003543
739173	H600 4592P8 2200U6x24SIL 2CZS 0217	10.05.2022	81	Nachfolger/replacement 2003547
739176	H600 4592P8 1900F3x16SIL 2C 0205	06.05.2022	81	Nachfolger/replacement 2003487
739452	H600 AL 4092P8 380U4,5x20STS KOKU	28.02.2022	81	Nachfolger/replacement 2003567
739453	H600 AL 4592P8 380U4,5x20STS KOKU	10.05.2022	81	Nachfolger/replacement 2003568

764656	H600 5092P8 2200F3x16SIL 2CB 0203 VZS	11.05.2022	80	kein Nachfolger/no replacement
767057	H600 5092P8 2200F2x16SIL 4E 2225 VE100	11.05.2022	99	Nachfolger/replacement 2003477
767058	H600 5092P8 2200F3x16SIL 2CH 0203	11.05.2022	81	Nachfolger/replacement 2003524
769344	H600 5592P8 1900F3x20SIL 2C 0205	08.04.2022	80	kein Nachfolger/no replacement
769375	H600 5592P8 2200F3x20SIL 2C 0203	08.04.2022	80	kein Nachfolger/no replacement
769376	H600 5592P8 2400F3x20SIL 2C 0207	08.04.2022	80	kein Nachfolger/no replacement
769377	H600 5592P8 2100F3x20SIL 2C 0203 KO	08.04.2022	80	kein Nachfolger/no replacement
773229	H600 4594R8 1900F3x16SIL 2C 0205	31.05.2022	80	kein Nachfolger/no replacement
775121	H600 5594R8 2100U6x24STS 2C 0203 KO	30.06.2022	81	Nachfolger/replacement 2003871
780675	H600 5594R8 1900U6x24STS 2C 0205	30.06.2022	80	kein Nachfolger/no replacement
780717	H600 5092P8 2100U6x24SIL 2C 0203 VZS KO	11.05.2022	81	Nachfolger/replacement 2003499
782015	H600 5594R8 2200F3x20SIL 2CH 0203	30.06.2022	80	kein Nachfolger/no replacement
784997	H600 3594R8 2200F2x20SIL 4V 2225 ZUOV	30.06.2022	80	kein Nachfolger/no replacement
784998	H600 4594R8 2200F2x20SIL 4V 2225 ZUOV	31.05.2022	81	Nachfolger/replacement 2003833
784999	H600 5594R8 2200F2x20SIL 4V 2225 ZUOV	30.06.2022	81	Nachfolger/replacement 2003834
785000	H600 6594R8 2200F2x20SIL 4V 2225 ZUOV	30.06.2022	80	kein Nachfolger/no replacement
785038	H600 3594R8 2200F3x16SIL 2C 0203	30.06.2022	81	Nachfolger/replacement 2003835
785039	H600 4594R8 2200F3x16SIL 2C 0203	31.05.2022	81	Nachfolger/replacement 2003837
785040	H600 5594R8 2200F3x16SIL 2C 0203	30.06.2022	81	Nachfolger/replacement 2003839
785041	H600 6594R8 2200F3x16SIL 2C 0203	30.06.2022	81	Nachfolger/replacement 2003840
785042	H600 3594R8 2200F3x20SIL 2C 0203	30.06.2022	81	Nachfolger/replacement 2003847
785043	H600 4594R8 2200F3x20SIL 2C 0203	31.05.2022	99	Nachfolger/replacement 2003849
785044	H600 5594R8 2200F3x20SIL 2C 0203	30.06.2022	81	Nachfolger/replacement 2003851
785095	H600 6594R8 2200F3x20SIL 2C 0203	30.06.2022	81	Nachfolger/replacement 2003852
785699	H600 3592P8 2100F3x16SIL 2C 0203 KO	30.03.2022	81	Nachfolger/replacement 2003493
785700	H600 3592P8 2400F3x16SIL 2C 0207	30.03.2022	81	Nachfolger/replacement 2003488
787962	H600 3594R8 1900F3x20SIL 2C 0205	30.06.2022	80	kein Nachfolger/no replacement
787963	H600 4594R8 1900F3x20SIL 2C 0205	31.05.2022	99	kein Nachfolger/no replacement
787964	H600 5594R8 1900F3x20SIL 2C 0205	30.06.2022	80	kein Nachfolger/no replacement
787965	H600 6594R8 1900F3x20SIL 2C 0205	30.06.2022	80	kein Nachfolger/no replacement
792327	H600 4092P8 2200F2x16SIL 2CH2V 5253 ZOZU	28.02.2022	81	Nachfolger/replacement 2003556
793115	H600 5092P8 2200F3x16SIL 2CB 0203	11.05.2022	99	kein Nachfolger/no replacement
793116	H600 5094R8 2200F3x16SIL 2CB 0203	30.06.2022	80	kein Nachfolger/no replacement
793117	H600 5092P8 404F2x16SIL KOKU	11.05.2022	81	Nachfolger/replacement 2003427
793118	H600 5094R8 404F2x16SIL KOKU	30.06.2022	81	Nachfolger/replacement 2003828
796365	H600 6592P8 404F2x16SIL KOKU	30.06.2022	81	Nachfolger/replacement 2003429

798077	H600 6592P8 1120F2x16SIL 1K 0073	30.06.2022	81	Nachfolger/replacement 2003559
798078	H600 6592P8 990F2x16SIL 1K 4000 OF	30.06.2022	81	Nachfolger/replacement 2003560
799068	H600 3592P8 2200F3x16SIL 4C 0817 VE100	30.03.2022	80	kein Nachfolger/no replacement
799206	H600 5592P8 2050F2x16SIL 2C2V 6089 ZOZU	08.04.2022	80	kein Nachfolger/no replacement
799874	H600 AL 3592P8 380U4,5x20STS KOKU	30.06.2022	81	Nachfolger/replacement 2003563
808591	H600 6594R8 1900F3x16SIL 2C 0205	30.06.2022	80	kein Nachfolger/no replacement
808643	H600 4094R8 404F2x16SIL KOKU	30.06.2022	81	Nachfolger/replacement 2003827
808644	H600 3592P8 1900F3x16SIL 2C 0205	30.03.2022	81	Nachfolger/replacement 2003486
811547	H600 5094R8 1900U6x24SIL 2C 0205	30.06.2022	80	kein Nachfolger/no replacement
811548	H600 5094R8 2100U6x24SIL 2C 0203 KO	30.06.2022	81	Nachfolger/replacement 2003862
811549	H600 5094R8 2400U6x24SIL 2C 0207	30.06.2022	80	kein Nachfolger/no replacement
811555	H600 5594R8 1900F3x16SIL 2C 0205	30.06.2022	80	kein Nachfolger/no replacement
812667	H600 5094R8 2200U6x24SIL 2C 0203	30.06.2022	81	Nachfolger/replacement 2003862
816968	H600 6594R8 2100F3x20SIL 2C 0203 KO	30.06.2022	81	Nachfolger/replacement 2003852
818637	H600 6592P8 2200F2x16SIL 4V 2225 ZUOV	30.06.2022	81	Nachfolger/replacement 2003454
821433	H600 5592P8 2200U6x24SIL 2C 0203	12.04.2022	81	Nachfolger/replacement 2003491
822158	H600 5592P8 2200F2x16SIL 4V 2225 ZUOV	12.04.2022	81	Nachfolger/replacement 2003453
822185	H600 4592P8 1988R3x20SIL 2H0207 S2VE100	06.05.2022	99	Nachfolger/replacement 2005632
822559	H600 3594R8 1900F3x16SIL 2C 0205	30.06.2022	80	kein Nachfolger/no replacement
822560	H600 4094R8 1900F3x16SIL 2C 0205	30.06.2022	80	kein Nachfolger/no replacement
822561	H600 5094R8 1900F3x16SIL 2C 0205	30.06.2022	80	kein Nachfolger/no replacement
822562	H600 3594R8 2200F3x16SIL 2C 0201	30.06.2022	81	Nachfolger/replacement 2003841
822563	H600 4094R8 2200F3x16SIL 2C 0201	30.06.2022	81	Nachfolger/replacement 2003842
822564	H600 4594R8 2200F3x16SIL 2C 0201	31.05.2022	81	Nachfolger/replacement 2003843
822565	H600 5094R8 2200F3x16SIL 2C 0201	30.06.2022	81	Nachfolger/replacement 2003844
822566	H600 5594R8 2200F3x16SIL 2C 0201	30.06.2022	81	Nachfolger/replacement 2003845
822567	H600 6594R8 2200F3x16SIL 2C 0201	30.06.2022	81	Nachfolger/replacement 2003846
822568	H600 3594R8 2100F3x16SIL 2C 0203 KO	30.06.2022	81	Nachfolger/replacement 2003835
822569	H600 4094R8 2100F3x16SIL 2C 0203 KO	30.06.2022	81	Nachfolger/replacement 2003836
822570	H600 5094R8 2100F3x16SIL 2C 0203 KO	27.06.2022	99	Nachfolger/replacement 2003838
822571	H600 4094R8 1900F3x20SIL 2C 0205	30.06.2022	80	kein Nachfolger/no replacement
822572	H600 5094R8 1900F3x20SIL 2C 0205	30.06.2022	80	kein Nachfolger/no replacement
822573	H600 3594R8 2200F3x20SIL 2C 0201	30.06.2022	81	Nachfolger/replacement 2003853
822574	H600 4094R8 2200F3x20SIL 2C 0201	30.06.2022	81	Nachfolger/replacement 2003854
822575	H600 4594R8 2200F3x20SIL 2C 0201	31.05.2022	99	Nachfolger/replacement 2003855
822576	H600 5094R8 2200F3x20SIL 2C 0201	30.06.2022	81	Nachfolger/replacement 2003856

822577	H600 5594R8 2200F3x20SIL 2C 0201	30.06.2022	81	Nachfolger/replacement 2003857
822578	H600 6594R8 2200F3x20SIL 2C 0201	30.06.2022	81	Nachfolger/replacement 2003858
822579	H600 3594R8 2100F3x20SIL 2C 0203 KO	30.06.2022	81	Nachfolger/replacement 2003847
822580	H600 4094R8 2100F3x20SIL 2C 0203 KO	30.06.2022	81	Nachfolger/replacement 2003848
822581	H600 4594R8 2100F3x20SIL 2C 0203 KO	31.05.2022	99	Nachfolger/replacement 2003849
822582	H600 5094R8 2100F3x20SIL 2C 0203 KO	30.06.2022	81	Nachfolger/replacement 2003850
822583	H600 5594R8 2100F3x20SIL 2C 0203 KO	30.06.2022	81	Nachfolger/replacement 2003851
822584	H600 3594R8 1900U6x24SIL 2C 0205	30.06.2022	80	kein Nachfolger/no replacement
822585	H600 4094R8 1900U6x24SIL 2C 0205	30.06.2022	80	kein Nachfolger/no replacement
822586	H600 4594R8 1900U6x24SIL 2C 0205	31.05.2022	99	kein Nachfolger/no replacement
822587	H600 5594R8 1900U6x24SIL 2C 0205	30.06.2022	80	kein Nachfolger/no replacement
822588	H600 6594R8 1900U6x24SIL 2C 0205	30.06.2022	80	kein Nachfolger/no replacement
822589	H600 3594R8 2200U6x24SIL 2C 0201	30.06.2022	81	Nachfolger/replacement 2003865
822590	H600 4094R8 2200U6x24SIL 2C 0201	30.06.2022	81	Nachfolger/replacement 2003866
822591	H600 4594R8 2200U6x24SIL 2C 0201	31.05.2022	99	Nachfolger/replacement 2003867
822592	H600 5094R8 2200U6x24SIL 2C 0201	30.06.2022	81	Nachfolger/replacement 2003868
822593	H600 5594R8 2200U6x24SIL 2C 0201	30.06.2022	81	Nachfolger/replacement 2003869
822594	H600 6594R8 2200U6x24SIL 2C 0201	30.06.2022	81	Nachfolger/replacement 2003870
822595	H600 3594R8 2100U6x24SIL 2C 0203 KO	30.06.2022	81	Nachfolger/replacement 2003859
822596	H600 4094R8 2100U6x24SIL 2C 0203 KO	30.06.2022	81	Nachfolger/replacement 2003860
822597	H600 4594R8 2100U6x24SIL 2C 0203 KO	31.05.2022	99	Nachfolger/replacement 2003861
822598	H600 5594R8 2100U6x24SIL 2C 0203 KO	30.06.2022	81	Nachfolger/replacement 2003863
822599	H600 6594R8 2100U6x24SIL 2C 0203 KO	30.06.2022	81	Nachfolger/replacement 2003864
839649	H600 4592P8 2200F2x20SIL 4V 2225 VE100	10.05.2022	81	Nachfolger/replacement 2003465
858923	H600Lock 92/8/PZ DM44Profile	in clarification	81	Nachfolger/replacement 2005713
890981	H600 5092P8 1900U6x24SIL 2C 0205	11.05.2022	81	Nachfolger/replacement 2003492
890982	H600 4592P8 2400F3x16SIL 2CB 0207	06.05.2022	81	Nachfolger/replacement 2003509
890983	H600 4592P8 1900F3x16SIL 2CB 0205	06.05.2022	99	Nachfolger/replacement 2003508
891321	H600 2892P8 2200F3x20SIL 2CH 0203	21.04.2022	81	Nachfolger/replacement 2003527
891327	H600 4592P8 2400F3x16SIL 2CH 0207	10.05.2022	81	Nachfolger/replacement 2003526
896078	H600 4592P8 1900F3x20SIL 2CB 0205	06.05.2022	81	Nachfolger/replacement 2003511
896079	H600 4592P8 2400F3x20SIL 2CB 0207	06.05.2022	81	Nachfolger/replacement 2003512
899206	H600 2892P8 1900F3x20SIL 2CH 0205	21.04.2022	81	Nachfolger/replacement 2003528
899208	H600 2892P8 2400F3x20SIL 2CH 0207	26.04.2022	81	Nachfolger/replacement 2003529
899295	H600 4594R8 2400F3x16SIL 2C 0207	31.05.2022	80	kein Nachfolger/no replacement
899689	H600 3592P8 2200F3x20SIL 2C 0203 SYK	30.03.2022	81	Nachfolger/replacement 2003569



Created on 22.02.2022

Modified on 22.02.2022

No. 20 2885

899692	H600 3592P8 2200U6x24STS 2CB 0203 SYK	30.03.2022	81	Nachfolger/replacement 2003571
899693	H600 3592P8 2200U6x24SIL 2CH 0203 SYK	30.03.2022	81	Nachfolger/replacement 2003572
899700	H600 3592P8 2200U6x24STS 2C 0203 SYK	30.03.2022	81	Nachfolger/replacement 2003570
2002068	H600 4592P8 2400F3x16SIL 2C 0207	10.05.2022	81	Nachfolger/replacement 2003489
795199	H600 4592P8 2200F2x16SIL 2K 4849 VE100	02.05.2022	81	Nachfolger/replacement 2003561
733335	H600 3592P8 2100F3x16SIL 2CB 0203 KO	30.03.2022	81	Nachfolger/replacement 2003516
899694	H600 3592P8 2200U6x24STS 2CH 0203 SYK	30.03.2022	81	Nachfolger/replacement 2003573