



Created on 18.08.2021  
Modified on 18.08.2021

No. 21 2123

## Product Information

Product Brand: Roto Safe

Phase out E510 Eneo C

### Related Products

Roto Safe  
Discontinued Product

### Availability / Ordering ability

Because of the low sales, no more components can be procured.  
Therefore, the E510 Eneo C locks listed below are removed from the program.

Phase out date: with immediate effect respectively remainders are used up

Spare parts: are not intended

Return shipments are not possible.

### Product Overview Outlet

Material No.	Description	Phase-Out Date	Target CPMS	Note
563117	E510 5592P8 1988R3x20SIL 2H 02+E07 ON L	18.08.2021	99	kein Nachfolger/no replacement
563118	E510 5592P8 1988R3x20SIL 2H 02+E07 ON R	18.08.2021	99	kein Nachfolger/no replacement
627329	E510 6592P10 2200F3x20SIL 2C 02+E03 ON L	18.08.2021	99	kein Nachfolger/no replacement
627330	E510 6592P10 2200F3x20SIL 2C 02+E03 ON R	18.08.2021	80	kein Nachfolger/no replacement
627333	E510 5592P8 2200F3x16SIL 2C 02+E03 ON L	18.08.2021	99	kein Nachfolger/no replacement
627334	E510 5592P8 2200F3x16SIL 2C 02+E03 ON R	18.08.2021	80	kein Nachfolger/no replacement
633253	E510 4592P10 2200U6x24SIL 2C 02+E03 ON L	18.08.2021	99	kein Nachfolger/no replacement
633254	E510 4592P10 2200U6x24SIL 2C 02+E03 ON R	18.08.2021	99	kein Nachfolger/no replacement
633454	E510 3592P8 2200U6x24STS 2C 02+E03 ON L	18.08.2021	80	kein Nachfolger/no replacement
633455	E510 3592P8 2200U6x24STS 2C 02+E03 ON R	18.08.2021	99	kein Nachfolger/no replacement
633520	E510 5592P8 2200F3x20SIL 2C 02+E03 ON L	18.08.2021	81	Nachfolger/replacement 817026
633521	E510 5592P8 2200F3x20SIL 2C 02+E03 ON R	18.08.2021	81	Nachfolger/replacement 817026
635662	E510 4592P8 2200F3x16SIL 2C 02+E03 ON L	18.08.2021	80	kein Nachfolger/no replacement
635663	E510 4592P8 2200F3x16SIL 2C 02+E03 ON R	18.08.2021	80	kein Nachfolger/no replacement
636522	E510 4592P8 2200U6x24STS 2C 02+E03 ON L	18.08.2021	99	kein Nachfolger/no replacement
636523	E510 4592P8 2200U6x24STS 2C 02+E03 ON R	18.08.2021	99	kein Nachfolger/no replacement
779840	E510 5592P8 2400F3x20SIL 2C 02+E07 ON L	18.08.2021	99	Nachfolger/replacement 817027



Created on 18.08.2021  
Modified on 18.08.2021

No. 21 2123

779841 E510 5592P8 2400F3x20SIL 2C 02+E07 ON R

18.08.2021 81

Nachfolger/replacement 817027

---