

## Product Information

Product Brand: Roto Safe

Phase out Safe P articles

### Related Products

Roto Safe  
Discontinued Product

### Availability / Ordering ability

The locks listed below will be removed from the program.  
Please note that for panic variants P600 and P650 only combination locks are offered and used.

Phase out date: with immediate effect

Spare parts: are not provided

Return deliveries are not possible!

### Product Overview Outlet

Material No.	Description	Phase-Out Date	Target CPMS	Note
611432	P600 3592P9 2200F3x20SIL 2CB 0203	05.10.2023	85	kein Nachfolger / no replacement
611436	P600 3592P9 2200F3x20SIL 2CH 0203	05.10.2023	99	kein Nachfolger / no replacement
611438	P600 3592P9 2200F3x24SIL 2CB 0203	05.10.2023	99	kein Nachfolger / no replacement
611442	P600 3592P9 2200F3x24SIL 2CH 0203	05.10.2023	99	kein Nachfolger / no replacement
611444	P600 3592P9 2200U6x24SIL 2CB 0203	05.10.2023	99	kein Nachfolger / no replacement
611448	P600 3592P9 2200U6x24SIL 2CH 0203	05.10.2023	99	kein Nachfolger / no replacement
611449	P600 3592P9 2200U6x24STS 2CH 0203	05.10.2023	99	kein Nachfolger / no replacement
611450	P600 4092P9 2200F3x16SIL 2CB 0203	05.10.2023	99	kein Nachfolger / no replacement
611454	P600 4092P9 2200F3x16SIL 2CH 0203	05.10.2023	99	kein Nachfolger / no replacement
611455	P600 4092P9 2200F2x16STS 2CH 0203	05.10.2023	99	kein Nachfolger / no replacement
611456	P600 4092P9 2200F3x20SIL 2CB 0203	05.10.2023	99	kein Nachfolger / no replacement
611460	P600 4092P9 2200F3x20SIL 2CH 0203	05.10.2023	99	kein Nachfolger / no replacement
611462	P600 4092P9 2200F3x24SIL 2CB 0203	05.10.2023	99	kein Nachfolger / no replacement
611466	P600 4092P9 2200F3x24SIL 2CH 0203	05.10.2023	99	kein Nachfolger / no replacement

611468	P600 4092P9 2200U6x24SIL 2CB 0203	05.10.2023	99	kein Nachfolger / no replacement
611472	P600 4092P9 2200U6x24SIL 2CH 0203	05.10.2023	99	kein Nachfolger / no replacement
611498	P650 3592P9 2200F3x20SIL 2CB 0203	05.10.2023	99	kein Nachfolger / no replacement
611502	P650 3592P9 2200F3x20SIL 2CH 0203	05.10.2023	99	kein Nachfolger / no replacement
611504	P650 3592P9 2200F3x24SIL 2CB 0203	05.10.2023	99	kein Nachfolger / no replacement
611508	P650 3592P9 2200F3x24SIL 2CH 0203	05.10.2023	99	kein Nachfolger / no replacement
611510	P650 3592P9 2200U6x24SIL 2CB 0203	05.10.2023	99	kein Nachfolger / no replacement
611514	P650 3592P9 2200U6x24SIL 2CH 0203	05.10.2023	99	kein Nachfolger / no replacement
611516	P650 4092P9 2200F3x16SIL 2CB 0203	05.10.2023	99	kein Nachfolger / no replacement
611520	P650 4092P9 2200F3x16SIL 2CH 0203	05.10.2023	99	kein Nachfolger / no replacement
611522	P650 4092P9 2200F3x20SIL 2CB 0203	05.10.2023	99	kein Nachfolger / no replacement
611526	P650 4092P9 2200F3x20SIL 2CH 0203	05.10.2023	99	kein Nachfolger / no replacement
611528	P650 4092P9 2200F3x24SIL 2CB 0203	05.10.2023	99	kein Nachfolger / no replacement
611532	P650 4092P9 2200F3x24SIL 2CH 0203	05.10.2023	99	kein Nachfolger / no replacement
611534	P650 4092P9 2200U6x24SIL 2CB 0203	05.10.2023	99	kein Nachfolger / no replacement
611538	P650 4092P9 2200U6x24SIL 2CH 0203	05.10.2023	99	kein Nachfolger / no replacement
611540	P650 4592P9 2200F3x16SIL 2CB 0203	05.10.2023	99	kein Nachfolger / no replacement
611544	P650 4592P9 2200F3x16SIL 2CH 0203	05.10.2023	99	kein Nachfolger / no replacement
611546	P650 4592P9 2200F3x20SIL 2CB 0203	05.10.2023	80	kein Nachfolger / no replacement
611550	P650 4592P9 2200F3x20SIL 2CH 0203	05.10.2023	99	kein Nachfolger / no replacement
611552	P650 4592P9 2200F3x24SIL 2CB 0203	05.10.2023	99	kein Nachfolger / no replacement
611556	P650 4592P9 2200F3x24SIL 2CH 0203	05.10.2023	99	kein Nachfolger / no replacement
611558	P650 4592P9 2200U6x24SIL 2CB 0203	05.10.2023	99	kein Nachfolger / no replacement
611562	P650 4592P9 2200U6x24SIL 2CH 0203	05.10.2023	99	kein Nachfolger / no replacement
633784	P600 3592P9 2200F3x16SIL 2CB 0203	05.10.2023	80	kein Nachfolger / no replacement
633815	P600 3592P9 2200F3x16SIL 2CH 0203	05.10.2023	99	kein Nachfolger / no replacement
633835	P650 3592P9 2200F3x16SIL 2CB 0203	05.10.2023	99	kein Nachfolger / no replacement
633836	P650 3592P9 2200F3x16SIL 2CH 0203	05.10.2023	99	kein Nachfolger / no replacement
737015	P600 4592P9 2200F2x16STS 2CB 0203	05.10.2023	99	kein Nachfolger / no replacement
737016	P600 4592P9 2200F2x16STS 2CH 0203	05.10.2023	99	kein Nachfolger / no replacement
737031	P600 4592P9 2200F3x16SIL 2CB 0203	05.10.2023	80	kein Nachfolger / no replacement
737032	P600 4592P9 2200F3x16SIL 2CH 0203	05.10.2023	99	kein Nachfolger / no replacement
737034	P600 4592P9 2200F3x20SIL 2CB 0203	05.10.2023	99	kein Nachfolger / no replacement
737035	P600 4592P9 2200F3x20SIL 2CH 0203	05.10.2023	99	kein Nachfolger / no replacement
737037	P600 4592P9 2200F3x24SIL 2CB 0203	05.10.2023	99	kein Nachfolger / no replacement
737038	P600 4592P9 2200F3x24SIL 2CH 0203	05.10.2023	99	kein Nachfolger / no replacement



Created on 05.10.2023  
Modified on 05.10.2023

No. 23 2437

737043	P600 4592P9 2200U6x24SIL 2CB 0203	05.10.2023	99	kein Nachfolger / no replacement
737044	P600 4592P9 2200U6x24SIL 2CH 0203	05.10.2023	99	kein Nachfolger / no replacement